

## Under Review Notification

Raised By: W.Kennedy

Product #: D799-139-039

Date: 17.08.08

Product Name: Oil Drain Kit

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	PP Under Review	Product Specifications Under Review ("Bluefiles")		
D139-799-039	-039 kit	Y	Y	N	Y	Y	Y	Y	17-613	CHG# affected
	IIN-D139-799 Rev N	N	N	N	N	N	N	N	17-613	revision required
	ICA-D139-799 Rev 13	N	N	N	N	N	N	N	17-613	revision required
	MDL-D139-799 Rev R	N	N	N	N	N	N	N	17-613	revision required
<del>D5373-3/-9/-11</del>	<del>Rev D</del>	<del>Y</del>	<del>Y</del>	<del>N</del>	<del>Y</del>	<del>Y</del>	<del>Y</del>	<del>Y</del>	<del>17-613</del>	<del>change hose length</del>
<del>D5522-041/-042</del>	<del>Rev B</del>	<del>Y</del>	<del>Y</del>	<del>N</del>	<del>Y</del>	<del>Y</del>	<del>Y</del>	<del>Y</del>	<del>17-613</del>	<del>redesign required</del>

### Description of Issue:

Upon installation of D5522-041/-042 it was determined that the Oil Drain Kit leaks oil and does not drain in the desired time frame.  
- rework of the design is required

no new kits shall be shipped to customers until the changes have been incorporated.

### Distribution:

VP Operations

Director of Operations

Director Quality Assurance

Director of Engineering

Chief Engineer

Engineering Project Managers

Engineering Clerk

Customer Support Manager

Production Engineers

Production Planners

Purchasing Manager

Technical Support

Product Manager - Solutions Provider